





Rail Assembly

Fit Rail Insert as shown both ends.




Installation Types


There are 3 typical different ways to install the **Universal Connector** to a 50x50 hollow member.



Upright Fit




Outside Fit




Inside Fit

Rail Positions


When following the dimensions stated on Kwiktech drawings, the angles will be predefined by the **Universal Connector** placement and rail length. Just select the correct hole when fitting.




0°



0° - 22.5° Angles




33.75° - 45° Angles





60° Angle

Reading Drawings

When reading Kwiktech drawings the dimensions will refer to these centre positions on the **Universal Connector**.



Dimensions to here



28mm